

IN THE SPECIFICATION

In the original specification part number 71 was mistakenly associated with two different parts. The description of FIG. 23 associated part number 71 with a caster wheel and the description of FIG. 27 associated the identical part number 71 with the liner of a crib. The latter part number 71, the liner of a crib, has been renumbered in the specification and in FIG. 27 as part number 171 to eliminate potential confusion. A revised copy of the specification with this change is enclosed along with a revised FIG. 27.

When reviewing the drawings it was found that several parts were label differently than in the specification than on FIG. 27 and FIG. 28.. We believe that this may have caused the examiners comments regarding the difficulty in understanding the concept of the inventions. We have corrected these errors as listed below and have attached a corrected copy of FIG. 27 and FIG. 28 to this office action.

Corrections to Figures in Specification

Figure	Changes noted
FIG. 27	1 Cross support arm attached to lower corner bracket 60B and upper corner bracket 40D labeled 350H
	2 Two cross support arms were labeled 350D - Cross support arm attached to lower corner bracket 60D and upper corner bracket 40A relabelled to 350F
	3 The liner in the drawing was number 71 which is the same number given to the casters in FIG. 23 - The liner has been renumbered as 171 to avoid confusion. The reference to the liner number in the specification has also been changed to 171.
FIG. 28	1 Cross support arm 50A is relabeled to 350A as stated in specification
	2 Cross support arm 50C is relabeled to 350B as stated in specification and to maintain consistent cross support arm labeling.
	3 Cross support arm 50E is relabeled to 350E as stated in specification
	4 Cross support arm 50F is relabeled to 350F as stated in specification